STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING 355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340

Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENE	ERAL INFORMATION		
1.	Report Time Period: From (mo./yr.) Jan.1,1990 To (mo./yr.) Dec.31,1990		
2.	DOGM File Number (original notice): M /021 / 005		
3.	Mine Name: Comstock , Blowout , Duncan		
4.	Legal Description (Location of Lands Affected):		
Comstock	NW 1/4, NE 1/4, Section 30 , Township 36 S , Range 13 W SLBM		
Blowout	1/4, _NE1/4, Section2, Township _36 S, Range1 WSLEM		
Duncan	1/4, _NE1/4, Section3 _, Township _36 S _, Range _14 W _SLBM		
5.	Mineral(s) Mined: Iron Ore		
6.	Name of Operator or Company:Geneva Steel		
7.	Permanent Address: P.O. Box 2500		
	Provo, Utah 84603		

8.	Company Representative (or designated operator):			
	Name: W. Roy Benson			
	Title: Division Manager - Mining			
	Address: RFD #1 Box 20-B, Santaquin, Utah 84655			
	Phone: 801-465-2532			
	Please check if any of the above information has changed since previous year.			
II.	MINING AND RECLAMATION .			
1.	Was the mine active during the past year? Yes \ No \ \ \ \ \ \ Months			
2.	If active, how much ore or mineral was mined?			
3.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage affected. Mining was restricted to the existing pit area. Lean ore was			
	stockpiled on existing disturbed areas. The waste dump encroached			
	approximately 1 acre over undisturbed to moderately disturbed ground			
4.	Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results. None.			
5.	What was the total unreclaimed acreage at years end? 266 acres			

6.	Briefly summarize mining and reclamation planned for the upcoming year.				
	Continue to mine in the existing pit limits with waste and				
	lean ore being piled in designated areas. Collect some topsoil				
-	prior to impacting new waste areas.				
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .				
III. ADDITIONAL INFORMATION					
1.	An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.				
2.	Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.				
IV. SIGNATURE REQUIREMENT					
I hereby certify that the foregoing is true and correct.					
,	Name (Typed or Print):	W. Roy Benson			
	Title of Operator:	Division Manager - Mining			
	Signature of Operator:	W. Lay Benson			
	Date:1-10-91	<u>.</u>			

jb MNMR-AR